

# Technical Update: Dipper® Urinalysis Dipstick Control

Lots #44551

Tech number: 164-18-44-1

Users: All Dipper Urinalysis Dipstick Control Users • Date issued: 06/13/18

---



## English

Endogenous crystalline sediment may be present and does not affect the performance of the product.

## German

Endogenes kristallines Sediment kann vorhanden sein und beeinträchtigt die Leistung des Produkts nicht.

## French

Des sédiments cristallins endogènes peuvent être présents, mais ils n'affectent pas la performance du produit.

## Italian

Possono essere presenti sedimenti cristallini endogeni; tali sedimenti non influiscono sulle prestazioni del prodotto.

## Spanish

El sedimento cristalino endógeno puede estar presente y no afectar al rendimiento del producto.

This area is intentionally left blank.