

Technical Update: Dipper® Urinalysis Dipstick Control

Lot #44791

Tech number: 234-19-44-1

Users: All Users of Dipper Urinalysis Dipstick Control Lot 44791 • Date issued: 08/23/19



English

Endogenous crystalline sediment may be present and does not affect the performance of the product.

German

Endogenes kristallines Sediment kann vorhanden sein und beeinträchtigt die Leistung des Produkts nicht.

French

Des sédiments cristallins endogènes peuvent être présents, mais ils n'affectent pas la performance du produit.

Italian

Possono essere presenti sedimenti cristallini endogeni; tali sedimenti non influiscono sulle prestazioni del prodotto.

Spanish

El sedimento cristalino endógeno puede estar presente y no afectar al rendimiento del producto.

This area is intentionally left blank.